



Diagram shown with
Nut Style, O, Standard
Ferrule Nut

Union Tees

JACO Part No.	Cont.	Tube	MU.	Nut	Tube O.D.	Comp. Thd.	A	B	D	E	F	G	H	K	M	N	O	P	Q
70-2				O	1/8	5/16-24	±1/64	±1/64	+005 +010	+005 -000	±1/64	±1/64	±1/64	±1/64	±1/64	+005 +010	+005 -000	±010	±1/64
70-4				O	1/4	7/16-20	1-7/16	47/64	250	.330	.218	15/32	23/32	3/8	23/64	N/A	N/A	N/A	N/A
70-5				O	5/16	1/2-20	1-19/32	13/16	312	.380	.232	31/64	13/16	7/16	29/64	N/A	N/A	N/A	N/A
70-6				O	3/8	5/8-20	1-59/64	31/32	375	.460	.250	19/32	31/32	35/64	35/64	N/A	N/A	N/A	N/A
70-8				O	1/2	3/4-20	2-1/8	1-1/16	500	.590	.375	11/16	1-1/16	43/64	11/16	N/A	N/A	N/A	N/A
70-10				O	5/8	7/8-20	2-35/64	1-17/64	625	.715	.500	45/64	1-1/4	53/64	53/64	N/A	N/A	N/A	N/A
70-12				O	3/4	1-1/16-20	3-3/32	1-35/64	.750	.860	.625	13/16	1-35/64	1	1-1/16	N/A	N/A	N/A	N/A